


Hanover

Engineering Associates Inc

January 28, 2014



Mr. Jack Cahalan, Manager
Lower Saucon Township
3700 Old Philadelphia Pike
Bethlehem, PA 18015

RE: Inspection Conducted on January 28, 2014
Hanover Project LS90-7

Dear Mr. Cahalan:

The purpose of this letter is to report the results of the above-referenced inspection, which was conducted by me along with Allen Schleyer, Compliance Manager for IESI. The reporting of "mid-meeting" inspections such as this one was previously provided by this office via electronic mail to multiple recipients. Going forward, this reporting will be provided in this more formal letter form, with one (1) hard copy addressed as shown above and no carbon copies distributed by this office, unless otherwise directed.

The following items were noted during the inspection:

1. The Bethlehem Renewable Energy (BRE) plant was running.
2. The landfill flare was running at a flow rate of 1,145 Standard Cubic Feet per Minute (SCFM) and a temperature of 1,635 degrees Fahrenheit. Mr. Schleyer acknowledged that this was a relatively low flow rate that indicates that the BRE plant is "pulling (gas) hard".
3. The truck wash was not in use due to frozen conditions.
4. No mud, odors, or blowing litter were observed along Applebutter Road, the entrance driveway, or at the landfill office.
5. No blowing litter was observed within the landfill. No litter was observed in the trees within the perimeter fence. Windscreens were in place at the working face. Wind was blowing out of (from) the north/northwest at five to ten miles per hour (5 - 10 mph).
6. Garbage was being disposed of in Cell 4F. One (1) truck was off-loading, and none were waiting to off-load.
7. No excavation work was taking place at the north end of Cell 4E to generate cover material. Mr. Schleyer stated that they are balancing generating soil onsite with importing material.
8. In the area of new final capping on the south face, the ground was snow covered and its condition could not be observed.
9. Newly constructed Cell 4E Stage 2 is still sitting idle.
10. No additional movement of soil or rock on the face of the west high wall, since the last inspection, was evident.
11. No earth moving is taking place on the Fox property.
12. No areas of seeps were observed, and none were reported by Mr. Schleyer.

ROUTING

- Council
- Manager
- Asst. Mgr.
- Zoning
- Finance
- Police
- P. Works
- P/C
- P & R
- EAC
- Engineer
- Solicitor
- Planner
- Landfill
- EMC
- Other


Welpert
HEA01-28-14

13. Mr. Schleyer stated that he has not received, nor been made aware of, any odor complaints since the January 16, 2014 meeting.
14. The internal access road, noted to be muddy and dusty during the January 16, 2014 inspection, has been cleaned and is free of mud, dirt, and dust.
15. A patrol of Steel City was conducted, beginning at approximately 2:30PM. No landfill-related odors or sounds were observed.

If you have any comments or questions regarding any of the above, or find that you need additional information, please do not hesitate to call me immediately.

Respectfully,

HANOVER ENGINEERING ASSOCIATES, INC.

A handwritten signature in black ink, appearing to read "Chris Taylor", is written over the printed name.

Christopher A. Taylor, PG, HMI

cat:cat/dad

S:\Projects\Municipal\LSauconTwp\LS90-07-BeihLandfill\Docs\HESI landfill report of Jan 28, 2014 insp.doc