

ee

JUL 29 2016

LOWER SAUCON TOWNSHIP

July 25, 2016

IESI PA Bethlehem Landfill
c/o Mr. Don Hallock, District General Manager
2335 Applebutter Road
Bethlehem, PA 18015

Re: Engineer's Monthly Status Report
IESI PA Bethlehem Landfill
Lower Saucon Township, Northampton County
I.D. No. 100020

Dear Mr. Hallock:

This Engineer's Status Report is for the month of June. The Engineer's meeting was held at the landfill on Thursday, July 14. This report is informational only, without deadlines, and a response is required only if objections are taken to the items mentioned.

A. Pending Permit Applications

1. A major modification for the southeastern realignment was received on January 21, 2015.

B. Construction Schedule

1. Cell 4E, Stage 3, was being filled at the time of my visit. Average amount of waste accepted was approximately 1000 tons per day.
2. Cell 4E, Stage 4 cell construction (about 1.4 acres) in the northwest corner of the landfill will start in the next week.
3. MSE berm construction, extending the wall westward, is also set to start next week.

C. Groundwater

1. Monitoring Wells: Total number of wells = 29
2. Abatement Wells: Total number of active wells = 10

D. Gas Management

1. There are 140 vertical gas wells currently installed. There are 41 horizontal collectors in operation.
2. The flare was operating at approximately 1200 scfm and 1650°F on the morning of my visit.
3. The BRE plant restarted on July 6 and was operational at the time of my visit. Flow to BRE was approximately 2200 scfm at about 53% methane.

ROUTING

- Council Manager
- Asst. Mgr.
- Zoning
- Finance
- Police
- P. Works
- P/C
- P & R
- EAC
- Engineer
- Solicitor
- Planner
- Landfill

S

IC

web site

eng June 2016

Northeast Regional Office

Mr. Don Hallock

July 25, 2016

E. Leachate Management

1. Average daily leachate flow for June was 20,500 gallons. Total leachate generated for the month was 615,017 gallons, all of which went directly to the Bethlehem wastewater treatment plant.

F. Site Observations


1. Litter: No issues observed.
2. Odor: No offsite odors were detected at the time of this visit.
3. Daily Cover: No issues observed.
4. Intermediate Cover: No issues observed.

G. Miscellaneous:

Enclosed as part of this report is the monthly Engineer's Reports from IESI Landfill for June, which includes site operations, radiation monitoring, truck safety, leachate management, and report submittals.

If you have any questions concerning this report, please contact me.

Sincerely,



Susan E. French
Waste Management Program

Enclosure

cc: Nicholas Rogers, IESI PA Landfill (w/enc.)
Lower Saucon Township (w/enc.)
James B. Birdsall, P.E., Hanover Engineering (w/enc.)
Chris Taylor, Hanover Engineering (w/enc.)
Kevin N. Bodner, Martin and Martin, Inc. (w/enc.)

PADEP ENGINEER'S REPORT

June 2016

Date: July 14, 2016

1. Site Operations:
 - a. Average Daily Volume 1375
 - b. Maximum Daily Volume 1800
 - c. Permitted Area 201
 - d. Permitted Disposal area 127.5
 - e. Capped acres 71.8
 - f. Constructed acres 82.7

2. Radiation Monitoring: **June**
 - a. Number of trucks that tripped the monitor 2
 - b. Number of trucks **on hold** or rejected 0

3. Truck Safety & Overweight: **June**
 - a. Number of Overweight Trucks 10
 - b. Number of Trucks Rejected Due To Overweight 0

4. Leachate Management:
 - a. Type of Discharge **Direct to WWTP**
 - b. Total Leachate Generated gal. 615,017
 - c. Untreated Effluent Discharge to WWTP 100%
 - d. Average Daily Flow gal. 20,500
 - e. Leachate hauled Offsite 0%
 - f. Detection zone flow (Max/week in g/a/d) **June**
LMC-6 - (7.5) LMC-7 - (7) LMC-8 - (5.3) PS-1 - (<1) PS-2 - (<1) PS-3 - (<1)

5. Leachate Storage:
 - a. Total Influent Storage Capacity 1,490,000
 - b. 25% Influent Storage Capacity 372,500
 - c. Current Volume Stored **est. 20% Storm water for Dust Control**

6. Gas Management - Decommission 3 vertical 1 horizontal add 2 horizontal collectors
 - a. Number of vertical wells (LFG extraction wells and cleanouts) 140
 - b. Number of horizontal wells 41

7. Groundwater
 - a. Number of monitoring wells 29
 - b. Abatement wells (TW-1 shut off per DEP approval) 10

8. Reports Submitted:

Groundwater	Annual GW Trend Analysis	6/20/16
Leachate	Allentown WWTP Disposal Rt	6/20/16
Quarterly	2Q16 DEP Facility Report	7/20/16
Other	Form U Submittals	electronic submittal

